

## **VI. Open Dumps**

### **A. New Sites**

**Dupo Heike** – Photographs were presented from the initial inspection conducted by Michael Gates on March 10, 2020. The site is located at 360 McBride Ave. Dupo, Illinois. Stephen and Dixie Heike are the listed owner. The violations observed during this inspection was open dumping of mainly comingled tires, household junk and trash. An ACWN was sent on March 10, 2020. SCCHD will monitor this site

### **B. Sites to be Closed**

### **C. Referrals to State's Attorney**

None

## **VII. Landfill Inspections**

### **1. Belleville/J&R (02/01/2022)**

Photographs presented from the previous inspection conducted on February 1, 2022. Ongoing issues from previous inspection still present (mowing, fence line issues, flares). Ongoing settling continues causing a rolling effect and several bowls, there are no issues with cap integrity currently. No leachate seepage, methane gas migration, or vegetative stress detected onsite. Damage to the fence was observed. SCCHD will continue to monitor the site.

## **VIII. COMMENTS**

## **IX. OPEN MEETING**

A motion was made to open the meeting. Motion was seconded. The motion carried.